

**Asbestos Survey Report**  
**1047 Sopchoppy Hwy.****ACM****Building No.:** Not Assigned      **Location:** Sopchoppy, Fl. 32358

ACM - Asbestos Containing Material

lf - linear feet

NAD -No Asbestos Detected

NON-ACM - Non Asbestos Containing Material

sf -square feet

CH - Chrysotile, AM - Amosite

HA - Homogenous Area

ea - each

***Bulk Sample Summary***

Results of the bulk samples are summarized as follow. The sample locations are included with this. Laboratory sample analysis report are included with this.

<i>Sample No.</i>	<i>HA No.</i>	<i>HA Description</i>	<i>Room</i>	<i>Result</i>
7	3	Roof shingles	Front porch roof	
10	1	Drywall		NAD
11	1	Drywall		NAD
12	1	Drywall		NAD
13	2	Wall Shingles	Back side wall	NAD
14	2	Wall Shingles	Back side wall	NAD
15	2	Wall Shingles	Back side wall	NAD
17	4	Linoleum - 1	Room 5	20% CH
18	4	Linoleum - 1	Room 5	18% CH
19	5	Linoleum - 2	Room 2	15% CH
20	5	Linoleum - 2	Room 2	14% CH
21	5	Linoleum - 2	Room 2	16% CH
22	6	Linoleum - 3	Room 6	NAD
23	7	Linoleum - 4	Room 3	NAD
24	7	Linoleum - 4	Room 4	NAD